

INDEX TO PHOTOGRAPHIC EXHIBIT
DUANE MARINE CORPORATION SPCC HEARING

- A Entrance gate to facility showing one of large oil-water separators in lower left corner and illustrating lack of secondary containment either for separator or facility in general.
- B Two large oil-water separators, showing lack of secondary containment
- C Illustration of usage of large tractor-trailer tank trucks in non-transportation related mode. At least 4-5 such trucks are shown. To the left of the leftmost dumpster is the Arthur Kill.
- D Another illustration of tank truck used as temporary storage; Arthur Kill in background.
- E Truck loading/unloading area showing 250,000 gallon tank at left. No transfer secondary containment. Drums stacked at left without containment.
- F Tank truck loading area and miscellaneous, unprotected horizontally oriented tank, showing lack of secondary containment.
- G View of tank truck loading/unloading area showing lack of secondary containment.
- H View of facility showing two horizontal tanks lacking secondary containment.
- I View of drip protection provided for tractor-trailer tank truck.
- J View of 55 gallon drums stacked with inadequate curbing. Note upper row.

335008

